

Message

---

**From:** Benoit, Simonne T [Simonne.Benoit@arcelormittal.com]  
**Sent:** 1/14/2017 4:26:52 PM  
**To:** Beslow, Mike [beslow.mike@epa.gov]; sean.f.fitzgerald@uscg.mil  
**CC:** Doyle, Kevin [Kevin.Doyle@arcelormittal.com]  
**Subject:** Status update 009/010/001

Boom Changed:

- 15 bags total on 1/13 (includes both 001 and 009/010)

Observations:

- Observed 009/010 from 7:30AM – 9:00AM. All conditions appeared normal, occasional quarter sized pops of sheen would appear inside the booms, was contained. I observed National change the boom inside of the orange skirt, dock side, no issues.
- Observed 001 from 9:45AM-10:00AM. The outer boom had been tightened up against the wall and a sock had been put in the corner, effectively containing the area. Otherwise, all conditions appeared the same as on 1/13.

**Simonne T. Benoit** | Environmental Engineer  
ArcelorMittal Indiana Harbor LLC | ArcelorMittal USA LLC

MEU Environmental | 3001 Dickey Road, Sla. 001  
East Chicago, IN 46312

T +219 399 2109 | F +219 399 3211 | M +219 313 5069 | [www.arcelormittal.com](http://www.arcelormittal.com)